

Medical Equipment: Service & Repairs

Medical Supermarket works alongside Calibrate UK Ltd to provide a nationwide service, using trained engineers.

Calibrate U.K. Ltd is an ISO 9001:2008 registered company, accredited specifically for medical equipment calibration. We work closely with manufacturers and national governing bodies to ensure our methods are up to date. We provide a digital certification package and inventory helping your practice keep up with CQC regulations.

Prices for the services are as follows (all prices quoted exclude VAT)

Spirometer servicing & repairs (Carefusion/Microlab):

Service/calibration & assessment: £85 + VAT

New turbine & calibration: £145 + VAT

New transducer housing, cable & calibration: £185 + VAT

New printer & housing & calibration: £195 + VAT

Supply & fit a new battery & calibration: £115 + VAT

*If a repair is carried out there won't be an additional service/calibration charge for the item/s.

ECG machine servicing & repairs:

Service/calibration & assessment: £65 + VAT

Seca ECGs

Seca ECG battery replacement & service/calibration: £165 + VAT Seca CT6i ECG printer kit

printer housing replacement & service/calibration: £215 + VAT

GE Medical ECGs:

MAC 1200ST internal battery replacement & service/calibration: £175 + VAT

MAC 1200ST main battery replacement & service/calibration: £205 + VAT

MAC 1200ST printer housing replacement & service/calibration: £225 + VAT

Welch Allyn ECGs:

Repairs: cost to be confirmed upon inspection.

Other ECG machines:

Repairs: cost to be confirmed upon inspection.

If a repair is carried out there won't be an additional service/calibration charge for the item/s.

Blood pressure monitors:

24 hour blood pressure monitors: Service, calibration & inspection: £85 + VAT

Repairs: cost to be confirmed upon inspection.



Suction pumps:

Service/calibration & assessment: £85 + VAT

Replacement motor & pump: £205 + VAT

Other repairs: cost to be confirmed upon inspection.

If a repair is carried out there won't be an additional service/calibration charge for the item/s.

Nebulisers:

Service/calibration & assessment: £55 + VAT

Repairs: cost to be confirmed upon inspection.

Syringe drivers:

McKinley T34: Calibration: £145 + VAT

The service & or repair of T34 syringe drivers isn't currently provided.

On-site services & repairs

Vaccine fridges:

Vaccine fridge service: £135 + VAT

Vaccine fridge calibration: £89 + VAT

Vaccine fridge repair: cost to be confirmed upon inspection. (Inspection visit £89 + VAT)

Couches/Plinths:

On-site Service & assessment: £89 + VAT

Repairs: cost to be confirmed upon inspection.

*Any cancellations within 28 days of the appointment date are subject to a 50% cancellation charge.